

Serial No. 10/721,182

Docket No. K-0575

Amdt. dated February 11, 2008

Reply to Office Action of November 15, 2007

**AMENDMENTS TO THE SPECIFICATION:**

Please replace paragraph [0045] with the following amended paragraph:

[0045] Moreover, a blower assembly 56a for blowing out humid air in the dishwasher in progress and a detergent box assembly 56b storing a detergent are provided to an inside of the door 56. And, a gasket (not shown in the drawing) is provided to an inner circumference of the door 56 to make the door 56 adhere closely to cabinet 54 when the door 56 is closed.

Please replace paragraph [0081] with the following amended paragraph:

[0081] Moreover, when the second incline portion 78b is caught on the first incline portion 78a as the supporter 72 ascends over the predetermined height, the second hook 79b of the supporter 72, as shown in FIG. 10F, is locked to the first hook 79a of the guide panel 74 so that the supporter 72 is unable to further move upward.